



**Rajasthan RVUNL**  
**Electrical Engineering**  
**Electrical Machines**  
**Important Formula Notes**



# ELECTRICAL MACHINES (FORMULA NOTES)

## 1. Transformer:

- Gross cross-sectional area = Area occupied by magnetic material + Insulation material.
- Net cross sectional area = Area occupied by only magnetic material excluding area of insulation material.
- Hence for all calculations, net cross-sectional area is taken since majority  $\phi$ (flux) flows in magnetic material.

$$\phi = BA_n$$

- Specific weight of t/f =  $\frac{\text{Weight of Transformer}}{\text{KVA rating of Transformer}}$

- Staking/iron factor:

$$(k_s) = \frac{\text{Net cross sectional area}}{\text{Gross cross sectional area}}$$

- $k_s$  is always less than 1
- Gross CS area =  $A_G = \text{Length} \times \text{Breadth}$
- Net CS area =  $A_n = k_s \times A_G$
- Utilization factor of transformer core

$$= \frac{\text{Effective CS area}}{\text{Total CS area}} \quad \text{U.F. of cruciform core} = 0.8 \text{ to } 0.85.$$

- Flux =  $\frac{\text{mmF}}{\text{Reluctance}} = \phi_m \sin \omega t$
- According to faradays second law,

$$e_1 = -N_1 \frac{d\phi}{dt} = -N_1 \frac{d}{dt} (\phi_m \sin \omega t)$$

Instantaneous value of emf in primary

$$e_1 = N_1 \phi_m \omega \sin \left( \omega t - \frac{\pi}{2} \right)$$

- Transformer emf equations:

$$E_1 = 4.44 N_1 B_{\max} A_n f \quad \dots (i)$$

$$E_2 = 4.44 N_2 B_{\max} A_n f \quad \dots (ii)$$

- Emf per turn in Primary:

$$E_1 / N_1 = \frac{E_1}{N_1} = 4.44 B_{\max} A_n f$$

- Emf per turn in Secondary:

## Rajasthan RVUNL

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

$$II^{rv} = \frac{E_2}{N_2} = 4.44B_{max}A_n f$$

- Emf per turn on both sides of the transformer is same

$$\frac{E_1}{N_1} = \frac{E_2}{N_2} \Rightarrow \frac{E_1}{E_2} = \frac{N_1}{N_2} = \frac{1}{k}$$

$$\text{Transformation ratio} = K = \frac{E_2}{E_1} = \frac{N_2}{N_1}$$

$$\text{Turn ratio} = \frac{1}{K} = N_1 : N_2$$

- For an ideal two-winding transformer with primary voltage  $V_1$  applied across  $N_1$  primary turns and secondary voltage  $V_2$  appearing across  $N_2$  secondary turns:

$$\frac{V_1}{V_2} = \frac{N_1}{N_2}$$

- The primary current  $I_1$  and secondary current  $I_2$  are related by:

$$\frac{I_1}{I_2} = \frac{N_2}{N_1} = \frac{V_2}{V_1}$$

- For an ideal step-down autotransformer with primary voltage  $V_1$  applied across  $(N_1 + N_2)$  primary turns and secondary voltage  $V_2$  appearing across  $N_2$  secondary turns.

$$\frac{V_1}{V_2} = \frac{(N_1 + N_2)}{N_2}$$

- The primary (input) current  $I_1$  and secondary (output) current  $I_2$  are related by:

$$\frac{I_1}{I_2} = \frac{N_2}{(N_1 + N_2)} = \frac{V_2}{V_1}$$

- For a single-phase transformer with rated primary voltage  $V_1$ , rated primary current  $I_1$ , rated secondary voltage  $V_2$  and rated secondary current  $I_2$ , the volt ampere rating  $S$  is:

$$S = V_1 I_1 = V_2 I_2$$

- For a balanced m-phase with rated primary phase voltage  $V_1$  rated primary current  $I_1$ , rated secondary phase voltage  $V_2$  and rated secondary current  $I_2$ , the volt ampere rating  $S$  is:

$$S = mV_1 I_1 = mV_2 I_2$$

- The primary circuit impedance  $Z_1$  referred to the secondary circuit for an ideal transformer with  $N_1$  primary turns and  $N_2$  secondary turns is:


$$Z_{12} = Z_1 \left( \frac{N_2}{N_1} \right)^2$$

- During operation of transformer:

$$B_m \propto \frac{E_1}{f} \propto \frac{V_1}{f}$$


$$B_{max} = \text{Constant} \Rightarrow \frac{V_1}{f} = \text{Constant}$$

**Equivalent circuit of Transformer under No-Load condition:**



- No load current =  $I_0 = \bar{I}_\mu + \bar{I}_w = I_0 \angle -\phi_0$   
 $I_w = I_0 \cos \phi_0$   
 $I_\mu = I_0 \sin \phi_0$
- No load power =  $V_1 I_0 \cos \phi_0 = V_1 I_w = \text{Iron losses}$   
 $R_0 = \frac{V_1}{I_{w1}}; X_0 = \frac{V_1}{I_\mu} \Rightarrow I_w = \frac{\text{No load power}}{V_1}$

**Transferring from Secondary to Primary:**



$$I_2^2 R_2 = I_1^2 R_2^1$$

$$R_2^1 = R_2 \left( \frac{I_2}{I_1} \right)^2 = \frac{R_2}{K^2} \quad \therefore \quad R_2^1 = \frac{R_2}{K^2}$$

**From Primary to Secondary:**

$$I_1^2 R_1 = I_2^2 R_1^1$$

$$R_1^1 = \frac{I_1^2}{I_2^2} \times R_1 = R_1 K^2$$

- Total resistance ref to primary =  $R_1 + R_2^1$   
 $R_{01} = R_1 + \frac{R_2}{K^2}$
- Total resistance ref to secondary =  $R_2 + R_1^1$   
 $R_{02} = R_2 + K^2 R_1$
- Total Cu loss =  $I_1^2 R_{01}$  or  $I_2^2 R_{02}$

## Rajasthan RVUNL

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

**Per unit resistance drops:**

- P.U. primary resistance drop =  $\frac{I_1 R_1}{E_1}$
- P.U. secondary resistance drop =  $\frac{I_2 R_2}{E_2}$
- Total P.U. resistance drop ref to  $I^{ry} = \frac{I_1 R_{01}}{E_1}$
- Total P.U. resistance drop ref to  $II^{ry} = \frac{I_2 R_{02}}{E_2}$
- The P.U. resistance drops on both sides of the t/f is same

$$\frac{I_1 R_{01}}{E_1} = \frac{I_2 R_{02}}{E_2}$$

**Losses present in transformer:**

1. Copper losses: Transformer windings major losses
2. Iron losses: Transformer core
3. Stray load losses: Cu parts and Iron parts minor losses
4. Dielectric losses: Insulating materials.

**1. Cu losses in transformer:**

Total Cu loss =  $I_1^2 R_1 + I_2^2 R_2 = I_1^2 R_{01} = I_2^2 R_{02}$

- Rated current on  $I^{ry} = \frac{\text{VA rating of t / f}}{E_1}$
  - Similarly, current on  $II^{ry} = \frac{\text{VA rating of t / f}}{E_2}$
  - Cu losses  $\propto I_1^2$  or  $I_2^2$ . Hence these are called as variable losses.
  - P.U. full load Cu loss =  $\frac{\text{FL Cu loss in watts}}{\text{VA rating of t / f}} = \frac{I_1^2 R_{01}}{E_1 I_1}$
  - If VA rating of transformer is taken as base then P.U Cu loss  $\propto I_1^2$  as remaining terms are constant.
  - P.U. Cu loss at x(Loading factor) of FL =  $x^2 \times \text{PU FL Cu loss}$
  - $\left. \begin{array}{l} \text{PU resistance drop ref to } I^{ry} \\ \text{PU resistance ref to } I^{ry} \end{array} \right\} = \frac{I_1 R_{01}}{E_1} \times \frac{I_1}{I_1} = \frac{I_1^2 R_{01}}{E_1 I_1}$
- $\therefore$  PU resistance drop = PU Full Load Cu loss  
 % FL Cu loss = %R = %Resistance drop.

**Iron (or) Core losses in Transformer:**

**1. Hysteresis loss:**

**Steinmetz formula:**

## Rajasthan RVUNL

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

$$W_h = \eta B_{max}^x f V$$

Area under one hysteresis loop

where,

$\eta$  = Stienmetz coefficient

$B_{max}$  = Maximum flux density in transformer core.

$f$  = Frequency of magnetic reversal = supply frequency.

$V$  = Volume of core material

$x$  = Hysteresis coefficient (or) stienmetz exponent = 1.6 (Si or CRGO steel)

## 2. Eddy current loss:

$$W_e \propto R_{ce} \times I_e^2$$

As area decreases in laminated core resistance as a result conductivity decrease.

$$W_e = K(\text{Constant})B_{max}^2 f^2(\text{Supply freq.}) \times t^2(\text{Thickness of lamination})$$

(It is a function of  $\sigma$ )

During operation of transformer:

$$B_m \propto \frac{V_1}{f}$$

$$\text{Case(i): } \frac{V_1}{f} = \text{Constant, } B_{max} = \text{Constant}$$

$$W_e \propto f^2$$

$$W_e = Bf^2$$

$$\therefore \left. \begin{matrix} W_i = W_h + W_e \\ W_i = Af + Bf^2 \end{matrix} \right\} \text{When } B_{max} = \text{Constant}$$

$$\text{Case(ii): } \frac{V_1}{f} \neq \text{Constant, } B_{max} \neq \text{Constant}$$

$$W_e \propto \left(\frac{V_1}{f}\right)^2 f^2$$

$$W_e \propto V_1^2$$

$$W_i = W_h + W_e$$

$$W_i = \frac{AV_1^{1.6}}{f^{0.6}} + BV_1^2$$

## P.U. iron loss:

- P.U. iron loss =  $\frac{\text{Iron loss in watts}}{\text{VA rating of t / f}}$
- As VA rating is chosen as base then the P.U. iron loss are also constant at all load conditions.

## To find out constant losses:

- $W_0$  = Losses in t/f under no-load condition = Iron losses + Dielectric loss + no-load primary loss ( $I_0^2 R_1$ )

# Rajasthan RVUNL

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

- Constant losses =  $W_0 - I_{02}^2 R_1$   
Where,  $R_1$  = LV winding resistance.

### To find out variable losses:

- $W_{sc}$  = Loss in transformer under SC condition = Full Load Cu loss + stray load losses (Cu and Iron) + Iron losses in both windings.
- Variable losses =  $W_{sc}$  - Iron losses corresponding to  $V_{sc}$ .

### OC Test:

$$V_1 \text{ rated} \rightarrow W_i$$

### SC Test:

$$V_{sc} \rightarrow (W_i)_{sc}$$

$$W_i \propto V_1^2$$

$$\frac{W_i}{(W_i)_{sc}} = \left( \frac{V_1 \text{ rated}}{V_{sc}} \right)^2$$

$$(W_i)_{sc} = W_i \left( \frac{V_{sc}}{V_1 \text{ rated}} \right)^2$$

$$\therefore \text{Variable losses} = W_{sc} - (W_i)_{sc} \left( \frac{V_{sc}}{V_1 \text{ rated}} \right)^2$$

- Under the assumption that small amount of iron losses corresponds to  $V_{sc}$  and stray load losses are neglected the wattmeter reading in SC test can be approximately taken as FL Cu losses in the transformer.
- $W_{sc} \approx \text{FL Cu loss} \approx I_{sc}^2 \times R_{01}$

$$R_{01} = \frac{W_{sc}}{I_{sc}^2}$$

### Efficiency:

- Efficiency of transformer is given by

$$\eta = \frac{\text{output power}}{\text{input power}} = \frac{\text{output power}}{\text{input power} + \text{losses}}$$

$$= \frac{E_2 I_2 \cos \phi_2}{E_2 I_2 \cos \phi_2 + \text{FL Cu losses} + \text{Iron losses}}$$

$$\eta_{FL} = \frac{E_2 I_2 \cos \phi_2}{E_2 I_2 \cos \phi_2 + I_2^2 R_{02} + W_i}$$

$$\eta_{x \text{ of FL}} = \frac{x(E_2 I_2) \cos \phi_2}{x(E_2 I_2) \cos \phi_2 + x^2(I_2^2 R_{02}) + W_i}$$



- Transformer efficiency =  $\frac{KVA \times \cos \phi}{KVA \times \cos \phi + W_i + Cu \text{ losses}}$
  - Voltage drop in t/f at a specific load, p.f. =  $I_2 R_{02} \cos \phi_2 \pm I_2 X_{02} \sin \phi_2$
  - % Voltage regulation =  $\frac{I_2 R_{02} \cos \phi_2 \pm I_2 X_{02} \sin \phi_2}{V_2} \times 100 = \left( \frac{I_2 R_{02}}{V_1} \right) \cos \phi_2 \pm \left( \frac{I_2 R_{02}}{V_1} \right) \sin \phi_2$
- % Regulation =  $[(R_{PU}) \cos \phi_2 + (X_{PU}) \sin \phi_2] \times 100$

**Auto Transformer:**

- K of auto transformer =  $\frac{LV}{HV}$
- (KVA)<sub>induction</sub> =  $(V_1 - V_2) I_1$
- Input KVA =  $V_1 I_1$
- $\frac{(KVA)_{induction}}{\text{input KVA}} = \frac{(V_1 - V_2) I_1}{V_1 I_1} = 1 - \frac{LV}{HV} = 1 - K$
- ∴ (KVA)<sub>induction</sub> =  $(1 - K)$  input KVA
- (KVA)<sub>induction</sub> = Input KVA - (KVA)<sub>ind</sub>
- (KVA)<sub>conduction</sub> =  $K \times$  input KVA
- Wt. of conductor in section AB of auto t / f  $\propto (N_1 - N_2) I_1$
- Wt. of conductor in section BC of auto t / f  $\propto (I_1 - I_2) N_1$
- ∴ Total Wt. of conductor in auto t/f is
- $\propto I_1 (N_1 - N_2) N_1 + (N_2 - N_1) N_2$
- $\propto 2(N_1 - N_2) I_1$
- Total Wt. of conductor in 2 wdg transformer
- $\propto I_1 N_1 + I_2 N_2 \propto 2I_1 N_1$
- $\frac{\text{Wt. of conductor in an auto t / f}}{\text{Wt. of conductor in 2 wdg t / f}} = \frac{2(N_1 - N_2) I_1}{2N_1 I_1} = 1 - \frac{N_2}{N_1} = 1 - K$
- Wt. of conductor in auto t/f =  $(1 - K)$  (Wt. of conductor in 2 wdg t/f)
- Thus, saving of conductor material if auto-transformer is used} =  $K \times$  (Conductor wt. in 2 wdg transformer)
- (% FL losses)<sub>AT</sub> =  $(1 - K)(\% \text{ FL losses})_{2\text{wdg t/f}}$
- (%Z)<sub>AT</sub> =  $(1 - K)(\%Z)_{2\text{wdg t/f}}$
- (KVA)<sub>AT</sub> =  $\frac{1}{1 - K} (KVA)_{2\text{wdg t/f}}$



**2. DC Machines:**

S.No.		Lap winding	Wave winding
1.	Coil span:	$Y_{cs} = s/p$	$Y_{cs} = s/p$
2.	Back pitch	$Y_b = UY_{cs}$	$Y_b = UY_{cs}$
3.	Commutator pitch	$Y_c = 1$ for progressive winding $Y_c = -1$ for retrogressive winding	$Y_c = \frac{2(c+1)}{p}$ for progressive winding $Y_c = \frac{2(c+1)}{p}$ for retrogressive winding ( $Y_c$ must be integer)
4.	Front pitch	$Y_f = Y_b + 2$ for progressive winding $Y_f = Y_b - 2$ for retrogressive winding	$Y_f = 2Y_b - Y_b$
5.	Parallel paths	$A = P$	$A = 2$
6.	Conductor current	$I_c = \frac{I_a}{A}$	$I_c = \frac{I_a}{A}$
7.	No. of brushes	No. of brushes = $A = P$	No. of brushes = 2

S = No. of commutator segments

P = No. of poles

$U = \text{No. of coil sides/No. of poles} = \frac{2c}{s}$

C = No. of coils on the rotor

A = No. of armature parallel paths

$I_a$  = Armature current

- Distribution factor

$$(K_d) = \frac{\text{Phasor sum coil emf}}{\text{Arithmetic sum of coil emf}} = \frac{\text{Chord}}{\text{arc}} = \frac{2}{\pi}$$

- Pitch factor

$$(K_p) = \frac{\text{Electrical angle of coil}}{180^\circ} \times 100\%$$

- $\theta_{\text{electrical}}^\circ = \frac{P}{2} \theta_{\text{mechanical}}^\circ$

- Armature mmf/Pole(Peak),  $AT_a = \frac{ZI_a}{2AP}$

## Rajasthan RVUNL

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

- $AT$  (compensating winding) =  $\frac{zI_a}{2AP} \times \frac{\text{Pole arc}}{\text{Pole pitch}}$
  - $A_t$  (Inter pole) =  $AT_a + \frac{B_i}{\mu_0} I_{gi}$
- where  $B_i$  = flux density in inter pole air gap  
 $I_{gi}$  = Length of inter pole air gap,  
 $\mu_0 = 4\pi \times 10^{-7}$
- No of turns in each interpole,  

$$N_{\text{interpole}} = \frac{AT(\text{Inter pole})}{I_a}$$
  - The no. of compensating conductor per pole,  $\frac{N_{cw}}{\text{Pole}} = \frac{Z}{AP} \left( \frac{\text{Pole arc}}{\text{Pole pitch}} \right)$
  - The mechanical power that is converted is given by  $P_{conv} = T_{ind} \omega_m$   
 Where,  $T$  = Induced torque  
 $\omega_m$  = Angular speed of the machine rotor
  - The resulting electric power produced  $P_{conv} = E_a I_a$
  - The power balance equation of the DC machine is  $T_{ind} \omega_m = E_a I_a$
  - The induced emf in the armature is  $E_a = \frac{\phi Z N P}{60 A}$ .
  - Torque developed in DC machine,  $T_e = \frac{P Z}{2\pi A} \phi I_a$ .

Where  $\phi = \frac{\text{Flux}}{\text{Pole}}$ ,  $Z$  = Number of armature conductors,  $P$  = No. of poles,  $N$  = Speed in rpm,

$A$  = No. of armature parallel paths  $I_a$  = Armature current

- The terminal voltage of the DC generator is given by  $V_t = E_a - I_a R_a$
- The terminal voltage of the DC motor is given by  $V_t = E_a + I_a R_a$
- Speed regulation of DC machine is given by,  $SR = \frac{\omega_{n1} - \omega_{f1}}{\omega_{f1}} \times 100\% = \frac{N_{n1} - N_{f1}}{N_{f1}} \times 100\%$
- Voltage regulation,  $VR = \frac{V_{n1} - V_{f1}}{V_{f1}} \times 100\%$

**Shunt Generator:**

- For a shunt generator with armature induced voltage  $E_a$ , armature current  $I_a$  and armature resistance  $R_a$ , the terminal voltage  $V$  is:  
 $V = E_a - I_a R_a$
- The field current  $I_f$  for a field resistance  $R_f$  is:  $I_f = \frac{V}{R_f}$
- The armature induced voltage  $E_a$  and torque  $T$  with magnetic flux  $\phi$  at angular speed  $\omega$  are:

## Rajasthan RVUNL

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

$$E_a = k_f \Phi \omega = k_m \omega \quad T = k_f \Phi I_a = k_m I_a$$

Where,  $k_f$  and  $k_m$  are design coefficients of the machine.

Note that for a shunt generator:

- Induced voltage is proportional to speed.
- Torque is proportional to armature current.
- The airgap power  $P_e$  for shunt generator is:

$$P_e = \omega T = E_a I_a = k_m \omega I_a$$

### Series Generator:

- For a series generator with armature induced voltage  $E_a$ , armature current  $I_a$ , armature resistance  $R_a$  and field resistance  $R_f$ , the terminal voltage  $V$  is:

$$V = E_a - (I_a R_a + I_a R_f) = E_a - I_a (R_a + R_f)$$

The field current is equal to the armature current.

- The armature induced voltage  $E_a$  and torque  $T$  with magnetic flux  $\Phi$  at angular speed  $\omega$  are:

$$E_a = k_f \Phi \omega I_a = k_m \omega I_a$$

$$T = k_f \Phi I_a^2 = k_m I_a^2$$

Where  $k_f$  and  $k_m$  are design coefficient of the machine.

Note that for a series generator:

- Induced voltage is proportional to both speed and armature current,
- Torque is proportional to the square of armature current.
- Armature current is inversely proportional to speed for a constant  $E_a$
- The airgaps power  $P_e$  for a series generator is:

$$P_e = \omega T = E_a I_a = k_m \omega I_a^2$$

- Cumulatively compounded DC generator: (long shunt)

(a)  $I_a = I_f + I_L$

(b)  $V_t = E_a - I_a (R_a + R_s)$

(c)  $I_{sf} = \frac{V_x}{R_f} = \text{Shunt field current}$

- (d) The equivalent effective shunt field current for this machine is given by

$$I_{sf} = I_{sf} + \frac{N_{se}}{N_f} I_a - \left( \frac{\text{Armature reaction MMF}}{N_f} \right)$$

Where,  $N_{se}$  = No. of series field turns

$N_f$  = No of shunt field turns

- Differentially compounded DC generator: (long shunt)

(a)  $I_a = I_f + I_L$

(b)  $V_t = E_a - I_a (R_a + R_s)$

(c)  $I_{sf} = \frac{V_x}{R_f}$  = Shunt field current

(d) The equivalent effective shunt field current for this machine is given by

$$I_{sf} = I_{sf} - \frac{N_{se}}{N_f} I_a - \left( \frac{\text{Armature reaction MMF}}{N_f} \right)$$

Where,  $N_{se}$  = No. of series field turns

$N_f$  = No of shunt field turns

**Shunt Motor:**

- For a shunt generator with armature induced voltage  $E_a$ , armature current  $I_a$  and armature resistance  $R_a$ , the terminal voltage  $V$  is:

$$V = E_a + I_a R_a$$

The field current  $I_f$  for a field resistance  $R_f$  is:  $I_f = \frac{V}{R_f}$

- The armature induced voltage  $E_a$  and torque  $T$  with magnetic flux  $\Phi$  at angular speed  $\omega$  are:

$$E_a = k_f \Phi \omega = k_m \omega$$

$$T = k_f \Phi I_a = k_m I_a$$

Where,  $k_f$  and  $k_m$  are design coefficients of the machine.

Note that for a shunt motor:

- Induced voltage is proportional to speed.
- Torque is proportional to armature current.
- The airgap power  $P_e$  for shunt generator is:

$$P_e = \omega T = E_a I_a = k_m \omega I_a$$

- The speed of the shunt motor,  $\omega = \frac{V}{k\Phi} - \frac{R_a}{(K\Phi)^2 T}$  where,  $K = \frac{PZ}{2\pi A}$

**Series Motor:**

- For a series motor with armature induced voltage  $E_a$ , armature current  $I_a$ , armature resistance  $R_a$  and field resistance  $R_f$ , the terminal voltage  $V$  is:

$$V = E_a + (I_a R_a + I_a R_f) = E_a + I_a (R_a + R_f)$$

The field current is equal to the armature current.

- The armature induced voltage  $E_a$  and torque  $T$  with magnetic flux  $\Phi$  at angular speed  $\omega$  are:

$$E_a = k_f \Phi \omega I_a = k_m \omega I_a \quad T = k_f \Phi I_a^2 = k_m I_a^2$$

Where  $k_f$  and  $k_m$  are design coefficient of the machine.

Note that for a series motor:

- Induced voltage is proportional to both speed and armature current.
- Torque is proportional to the square of armature current.
- Armature current is inversely proportional to speed for a constant  $E_a$

- The airgap power  $P_e$  for a series motor is:

$$P_e = \omega T = E_a I_a = k_m \omega I_a^2$$

**Losses:**

- Constant losses ( $P_k$ ) =  $P_{wf} + P_{io}$   
where,  $P_{io}$  = No of load core loss
- Variables losses ( $P_v$ ) =  $P_c + P_{st} + P_b$   
Where,  $P_c$  = Copper losses =  $I_a^2 R_a$   
 $P_{st}$  = Stray load loss =  $dI_a^2$   
 $P_b$  = Brush contact drop =  $V_b I_a$ , where,  $V_b$  = Brush voltage drop
- The total machine losses,  $P_L = P_k + V_b I_a + K_v I_a^2$

**Efficiency:**

- The per unit efficiency  $\eta$  of an electrical machine with input power  $P_{in}$ , output power  $P_{out}$  and power loss  $P_{loss}$  is:

$$\eta = \frac{P_{out}}{P_{in}} = \frac{P_{out}}{(P_{out} + P_{loss})} = \frac{(P_{in} - P_{loss})}{P_{in}}$$

- Rearranging the efficiency equations:

$$P_{in} = P_{out} + P_{loss} = \frac{P_{out}}{\eta} = \frac{P_{loss}}{(1 - \eta)}$$

$$P_{out} = P_{in} - P_{loss} = \eta P_{in} = \frac{\eta P_{loss}}{(1 - \eta)}$$

$$P_{loss} = P_{in} - P_{out} = (1 - \eta) P_{in} = \frac{(1 - \eta) P_{out}}{\eta}$$

**Temperature Rise:**

- The resistance of copper and aluminum windings increases with temperature, and the relationship is quite linear over the normal range of operating temperatures. For a linear relationship, if the winding resistance is  $R_1$  at temperature  $\theta_1$  and  $R_2$  at temperature  $\theta_2$ , then:

$$\frac{R_1}{(\theta_1 - \theta_0)} = \frac{R_2}{(\theta_2 - \theta_0)} = \frac{(R_2 - R_1)}{(\theta_2 - \theta_1)}$$

where  $\theta_0$  is the extrapolated temperature for zero resistance.

- The ratio of resistances  $R_2$  and  $R_1$  is:

$$\frac{R_2}{R_1} = \frac{(\theta_2 - \theta_0)}{(\theta_1 - \theta_0)}$$

- The average temperature rise  $\Delta\theta$  of a winding under load may be estimated from measured values of the cold winding resistance  $R_1$  at temperature  $\theta_1$  (usually ambient temperature) and the hot winding resistance  $R_2$  at temperature  $\theta_2$ , using:

## Rajasthan RVUNL

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

$$\Delta\theta = \theta_2 - \theta_1 = \frac{(\theta_1 - \theta_0)(R_2 - R_1)}{R_1}$$

- Rearranging for per-unit change in resistance  $\Delta R_{pu}$  relative to  $R_1$ :

$$\Delta R_{pu} = \frac{(R_2 - R_1)}{R_1} = \frac{(\theta_2 - \theta_1)}{(\theta_1 - \theta_0)} = \frac{\Delta\theta}{(\theta_1 - \theta_0)}$$

### Copper Windings:

- The value of  $\theta_0$  for copper is  $-234.5^\circ\text{C}$ , so that:

$$\Delta\theta = \theta_2 - \theta_1 = (\theta_1 + 234.5) \frac{(R_2 - R_1)}{R_1}$$

- If  $\theta_1$  is  $20^\circ\text{C}$  and  $\Delta\theta$  is 1 degC:

$$\begin{aligned} \Delta R_{pu} &= \frac{(R_2 - R_1)}{R_1} \\ &= \frac{\Delta\theta}{(\theta_1 - \theta_0)} = \frac{1}{254.5} = 0.00393 \end{aligned}$$

- The temperature coefficient of resistance of copper at  $20^\circ\text{C}$  is 0.00393 per degC.

### Aluminium Windings:

- The value of  $\theta_0$  for aluminium is  $-228^\circ\text{C}$ , so that:

$$\Delta\theta = \theta_2 - \theta_1 = (\theta_1 + 228) \frac{(R_2 - R_1)}{R_1}$$

- If  $\theta_1$  is  $20^\circ\text{C}$  and  $\Delta\theta$  is 1 deg C:

$$\Delta R_{pu} = \frac{(R_2 - R_1)}{R_1} = \frac{\Delta\theta}{(\theta_1 - \theta_0)} = \frac{1}{248} = 0.00403$$

- The temperature coefficient of resistance of aluminium at  $20^\circ\text{C}$  is 0.00403 per deg C.

### Dielectric Dissipation Factor:

- If an alternating voltage  $V$  of frequency  $f$  is applied across an insulation system comprising capacitance  $C$  and equivalent series loss resistance  $R_s$ , then the voltage  $V_R$  across  $R_s$  and the voltage  $V_C$  across  $C$  due to the resulting current  $I$  are:

$$V_R = IR_s$$

$$V_C = IX_C$$

$$V = (V_R^2 + V_C^2)^{1/2}$$

- The dielectric dissipation factor of the insulation system is the tangent of the dielectric loss angle  $\delta$  between  $V_C$  and  $V$ :

$$\tan\delta = \frac{V_R}{V_C} = \frac{R_s}{X_C} = 2\pi fCR_s$$

$$R_s = X_C \tan\delta = \frac{\tan\delta}{2\pi fC}$$

- The dielectric power loss  $P$  is related to the capacitive reactive power  $Q_C$  by:

**Rajasthan RVUNL**

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

$$P = I^2R_s = I^2X_c \tan \delta = Q_c \tan \delta$$

- The power factor of the insulation system is the cosine of the phase angle  $\phi$  between  $V_R$  and  $V$ :

$$\cos \phi = \frac{V_R}{V}$$

So that  $\delta$  and  $\phi$  are related by:

$$\delta + \phi = 90^\circ$$

- $\tan \delta$  and  $\cos \phi$  are related by:

$$\tan \delta = \frac{1}{\tan \phi} = \frac{\cos \phi}{\sin \phi} = \frac{\cos \phi}{(1 - \cos^2 \phi)^{1/2}}$$

So that when  $\cos \phi$  is close to zero,

$$\tan \delta \approx \cos \phi$$

### 3. Synchronous Machines:

- Principle of operation:**

Whenever a conductor cuts the magnetic flux, an emf is induced in that conductor”  
-Faraday’s law of electromagnetic induction.

- Coil span ( $\beta$ ):** It is the distance between two sides of the coil. It is expressed in terms of degrees, pole pitch, no. of slots / pole etc.
- Pole pitch:** It is the distance between two identical points on two adjacent poles.  
Pole pitch is always  $180^\circ$  e = slots / pole.

- $\theta_{elec} = \frac{P}{2} \theta_{mech}$

- Slot pitch or slot angle:** (T) Slot angle is the angle for each slot.

- For a machine with ‘P’ poles and ‘s’ no. of slots, the slot angle =  $\gamma = \frac{P(180^\circ)}{d}$

$$\gamma = \frac{(180^\circ)}{(s / p)}$$

- Pitch factor or coil span factor or chording factor :- ( $K_p$ )

$$K_p = \frac{\text{The emf induced | Coil in short pitched winding}}{\text{The emf induced | Coil in full pitched winding}}$$

$$= \frac{\text{The vector sum of induced emf | Coil}}{\text{Arithmetic sum of induced emf | Coil}}$$

$$K_p = \frac{2E \cos \frac{\alpha}{2}}{2E} = \cos \frac{\alpha}{2}$$

- Pitch factor for  $n^{\text{th}}$  harmonic i.e.,  $K_{p_n} = \frac{\cos n \frac{\alpha}{2}}{2}$

- Chording angle to eliminate  $n^{\text{th}}$  harmonics

## Rajasthan RVUNL

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL



$$(\alpha) = \frac{180^\circ}{n}$$

- Coil span to eliminate  $n^{\text{th}}$  harmonics,  $(\beta) = 180 \left( \frac{n-1}{n} \right)$ .
- Distribution factor | Spread factor | belt factor | breadth factor ( $k_d$ ):

$$K_d = \frac{\text{The emf induced when the winding is distributed}}{\text{The emf induced when the winding is concentrated}}$$

$$= \frac{\text{Vector sum of emf induced}}{\text{Arithmetic sum of emf induced}}$$

$$K_d = \frac{\sin \frac{mY}{2}}{m \sin \frac{Y}{2}}$$

- The distribution factor for uniformly distributed winding is

$$k_{d4} = \frac{\sin \frac{mr}{2}}{\frac{mr}{2} \times \frac{\pi}{180}}$$

$$\text{For } n^{\text{th}} \text{ harmonic, } k_{dn} = \frac{\sin \frac{mnr}{2}}{m \sin \frac{ny}{2}}$$

- To eliminate  $n^{\text{th}}$  harmonics phase spread ( $m_y$ ) =  $\frac{360^\circ}{n}$
- Generally, KVA rating, power output  $\propto k_d$  and  $E_{ph}$  (induced emf)  $\propto k_d \times T_{ph}$

$$\therefore \frac{KVA_{60}(3-\phi)}{KVA_{120}(3-\phi)} = \frac{Pout_{60}(3\phi)}{Pout_{120}(3\phi)} = \frac{k_{d60}}{k_{d120}}$$

$$= \frac{\sin \frac{60}{2}}{\sin \frac{120}{2}} \times \frac{m_{120}}{m_{60}} = \frac{\sin 30^\circ}{\sin 60^\circ} \times \frac{120}{60} = 1.15$$

$$\frac{KVA_{60}(3\phi)}{KVA_{120}(2\phi)} = \frac{Pout_{60}(3\phi)}{Pout_{90}(2\phi)} = \frac{k_{d60}}{k_{d90}} = \frac{\sin \frac{60}{2}}{\sin \frac{90}{2}} \times \frac{90}{60} = 1.06$$

$$\frac{KVA_{60}(3\phi)}{KVA_{180}(1\phi)} = \frac{Pout_{60}(3\phi)}{Pout_{180}(1-\phi)} = \frac{k_{d60}}{k_{d180}} = \frac{\sin \frac{60}{2}}{\sin \frac{180}{2}} \times \frac{180}{60} = 1.5$$

$$\frac{KVA_{90}(2-\phi)}{KVA_{180}(1-\phi)} = \frac{Pout_{90}}{Pout_{180}} = \frac{k_{d90}}{k_{d180}} = \frac{\sin \frac{90}{2}}{\sin \frac{180}{2}} \times \frac{180}{90} = 1.414$$

- Speed of space harmonics of order  $(6k \pm 1)$  is  $\frac{1}{(6k \pm 1)} N_s$

where  $N_s = \text{Synchronous speed} = \frac{120f}{p}$

The order of slot harmonics is  $\left(\frac{2s}{p} \pm 1\right)$

where  $S = \text{No. of slots}$ ,  $P = \text{No. of poles}$

- Slot harmonics can be eliminated by skewing the armature slots and fractional slot winding. The angle of skew =  $\theta_s = \gamma$  (slot angle) = 2 harmonic pole pitches = 1 slot pitch.
- Distribution factor for slot harmonics,

$$k_d \left( \frac{2s}{p} \pm 1 \right)$$

Is  $k_{d1} = \frac{\sin \frac{m\gamma}{2}}{m \sin \frac{\gamma}{2}}$  i.e., same that of fundamental

- Pitch factor for slot harmonics,  $k_p \left( \frac{2s}{p} \pm 1 \right) = k_{p1} = \cos \frac{\alpha}{2}$
- The synchronous speed  $N_s$  and synchronous angular speed of a machine with  $p$  pole pairs running on a supply of frequency  $f_s$  are:

$$\omega_s = \frac{2\pi f_s}{p}$$

- Slip  $S = \frac{N_s - N}{N_s}$

Where  $N_s = \frac{120f}{p} = \text{synchronous speed}$

- The magnitude of voltage induced in a given stator phase is  $E_a = \sqrt{2}\pi N_c \phi f = K \phi \omega$  Where  $K = \text{constant}$
- The output power  $P_m$  for a load torque  $T_m$  is:
- The rated load torque  $T_M$  for a rated output power  $P_M$  is:

$$T_M = \frac{P_M}{\omega_s} = \frac{P_M p}{2\pi f_s} = \frac{120 P_M}{2\pi N_s}$$

**Synchronous Generator:**

- For a synchronous generator with stator induced voltage  $E_s$ , stator current  $I_s$  and synchronous impedance  $Z_s$ , the terminal voltage  $V$  is:

$$V = E - I_s Z_s = E_s - I_s (R_s + jX_s)$$

where  $R_s$  is the stator resistance and  $X_s$  is the synchronous reactance

## Rajasthan RVUNL

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

$$E = \sqrt{(V \cos \phi + I_a R_a)^2 + (V \sin \phi \pm I_a X_s)^2}$$

+  $\Rightarrow$  lag p.f.  
 -  $\Rightarrow$  leading p.f.

**Synchronous Motor:**

- For a synchronous motor with stator induced voltage  $E_s$ , stator current  $I_s$  and synchronous impedance  $Z_s$ , the terminal voltage  $V$  is:  
 $V = E_s + I_s Z_s = E_s + I_s (R_s + jX_s)$   
 where  $R_s$  is the stator resistance and  $X_s$  is the synchronous reactance

**Voltage regulation:**

- % regulation =  $\frac{|E| - |V|}{|V|} \times 100$   
 $E - V = I_a Z_s$   
 $\therefore$  % regulation =  $\frac{E - V}{V} = \frac{I_a Z_s}{V} \times 100$   
 $\therefore$  regulation  $\propto Z_s$   
 $\therefore$  As  $Z_s$  increases, voltage regulation increases.
- Condition for zero | min. voltage regulation is,  $\cos(\theta + \phi) = -\frac{I_a Z_s}{2V}$
- Condition for max. Voltage regulation is,  $\phi = \theta$
- Short circuit ratio (SCR)

$$\frac{I_{f_m}}{I_{f_a}} = \frac{1}{Z_s \text{ (adjusted)}_{\text{unit}}} = \frac{1}{X_s \text{ (adjusted)}_{\text{unit}}}$$

$$\text{SCR} \propto \frac{1}{X_a} \propto \frac{1}{\text{Armature reaction}}$$

Voltage regulation  $\propto$  Armature reaction

$$\therefore \text{SCR} \propto \frac{1}{\text{Voltage reaction}}$$

$\therefore$  Small value of SCR represents poor regulation.

$$\phi_a = \frac{\text{Armature mmf}}{\text{Reluctance}}$$

But reluctance  $\propto$  Air gap

$$\therefore \phi_a = \frac{\text{Armature mmf}}{\text{Airgap}}$$

$$\phi_a \propto \frac{1}{\text{Airgap length}}$$

$$\text{Armature reaction} \propto \phi_a \propto \frac{1}{\text{Airgap length}}$$

## Rajasthan RVUNL

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

$$\therefore \text{SCR} \propto \frac{1}{\text{Armature reaction}} \propto \text{Airgap length}$$

Air gap length  $\propto$  SCR

$\therefore$  Machine size  $\propto$  SCR Cost  $\propto$  SCR

$$\text{Power} = \frac{EV}{X_s} \sin \delta \Rightarrow P \propto \frac{1}{X_s} \propto \text{SCR}$$

Power  $\propto$  SCR

$\therefore$  Large value of SCR represents more power output.

- Synchronizing power coefficient or stability factor  $P_{sy}$  is given as

$$P_{sy} = \frac{dp}{d\delta} = \frac{d}{d\delta} \left( \frac{EV}{X_s} \sin \delta \right) = \frac{EV}{X_s} \cos \delta$$

$P_{sy}$  is a measure of stability

$\therefore$  Stability  $\propto P_{sy}$

But,  $P_{sy} \propto \frac{1}{X_s} \propto \text{SCR}$

$\therefore$  Stability  $\propto$  SCR

Stability  $\propto$  SCR  $\propto$  air gap length

$\therefore$  Stability  $\propto$  air gap length

- When the stator mmf is aligned with the d – axis of field poles then flux  $\phi_d$  per pole is set up and effective reactance offered by the alternator is  $X_d$ .

$$X_d = \frac{\text{Maximum voltage}}{\text{Minimum current}} = \frac{(V_t) \text{ line (at min, } I_a)}{\sqrt{3} I_a (\text{min})} = \text{Direct axis reactance}$$

- When the stator mmf is aligned with the q – axis of field poles then flux  $\phi_q$  per pole is set up and the effective reactance offered by the alternator is  $X_q$ .

$$X_q = \frac{\text{Minimum voltage}}{\text{Maximum current}} = \frac{(V_t) \text{ line (at min, } I_a)}{\sqrt{3} I_a (\text{max})} = \text{Quadrature axis reactance}$$

- Cylindrical rotor Synchronous machine,

The per phase power delivered to the infinite bus is given by  $P = \frac{E_f V_t}{X_s} \sin \delta$

- Salient pole synchronous machine,

The per phase power delivered to the infinite bus is given by

$$P = \frac{E_f V_t}{X_d} \sin \delta + \frac{V_t^2}{2} \left[ \frac{1}{X_q} - \frac{1}{X_d} \right] \sin 2\delta$$

Condition for max. power:

- For cylindrical rotor machine:

At constant  $V_t$  and  $E_f$ , the condition for max. power is obtained by putting  $\frac{dp}{d\delta} = 0$

$$\therefore \frac{dp}{d\delta} = \frac{E_f V_t}{X_s} \cos\delta = 0$$

$$\cos\delta = 0$$

$$\delta = 90^\circ$$

Hence maximum power occurs at  $\delta = 90^\circ$

- For salient – pole synchronous machine:

$$\frac{dp}{d\delta} = 0$$

$$\Rightarrow \frac{V_t E_f}{X_d} \cos\delta + V_t^2 \left( \frac{1}{x_q} - \frac{1}{x_d} \right) \cos 2\delta = 0$$

$$\cos\delta = -\frac{E_f X_q}{4V_t (X_d - X_q)} \pm \sqrt{\frac{1}{2} + \left[ \frac{E_f X_q}{4V_t (X_d - X_q)} \right]^2}$$

The value of load angle is seen to be less

than  $90^\circ$ .

$\therefore$  Maximum power occurs at  $\delta < 90^\circ$

- Synchronizing power =  $P_{sy} \cdot \Delta\delta = \frac{EV}{X_s} \cos\delta \Delta\delta$
- Synchronizing torque =  $\frac{\text{Synchronizing power}}{\omega}$

**Power flow in Alternator:**

- Complex power =  $S = P + jQ = VI_a^*$

Where Active power flow (P) =  $\frac{EV}{Z_s} \cos(\theta - \delta) - \frac{V^2}{Z_s} \cos\theta$ ;

Reactive power flow (Q) =  $\frac{EV}{Z_2} \sin(\theta - \delta) - \frac{V^2}{Z_s} \sin\theta$ ;

- Condition for max. power output:

$$P = \frac{EV}{Z_s} \cos(\theta - \delta) - \frac{V^2}{Z_2} \cos\theta$$

$$\frac{dp}{d\delta} = 0 \text{ for max power condition}$$

$$\text{i.e. } \theta - \delta = 0$$

$$\theta = \delta$$

If  $R_a = 0$ ;  $\theta = \delta = 90^\circ$ ; then max power is given by

$$P_{\max} = \frac{EV}{Z_s} - \frac{V^2}{Z_s} \cos\theta$$


## Rajasthan RVUNL

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

**4. Induction Machines:**

- The power flow diagram of 3 – φ induction motor is



The slip of induction machine is

$$(S) = \frac{n_s - n_r}{n_s} = \frac{N_s - N_r}{N_s}$$

Where  $N_s$  is synchronous speed in rpm  $n_s$  is synchronous speed in rps

$$\Rightarrow N_r = N_s(1 - s)$$

$$\Rightarrow N_s - N_r = sN_s$$

∴ Rotor frequency,

$$f_2 = \frac{P \times sN_s}{120} = S \frac{PN_s}{120} = Sf_1$$

For an induction machine with rotor resistance  $R_r$  and locked rotor leakage reactance  $X_r$ , the rotor impedance  $Z_r$  at slip  $s$  is:

$$Z_r = R_r + jsX_r$$

The stator circuit equivalent impedance  $Z_{rf}$  for a rotor/stator frequency ratio  $s$  is:

$$Z_{rf} = \frac{R_{rs}}{s + jX_{rs}}$$

For an induction motor with synchronous angular speed  $\omega_s$  running at angular speed  $\omega_m$  and slip  $s$ , the airgap transfer power  $P_t$ , rotor copper loss  $P_r$  and gross output power  $P_m$  for a gross output torque  $T_m$  are related by:

$$P_t = \omega_s T_m = \frac{P_r}{s} = \frac{P_m}{(1 - s)}$$

$$P_r = sP_t = \frac{sP_m}{(1 - s)}$$

$$P_m = \omega_m T_m = (1 - s)P_t$$

The power ratios are:

$$P_t : P_r : P_m = 1 : s : (1 - s)$$

The gross motor efficiency  $\eta_m$  (neglecting stator and mechanical losses) is:

## Rajasthan RVUNL

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

$$\eta_m = \frac{P_m}{P_t} = 1 - s$$

**Rotor emf, Current Power:**

At stand still, the relative speed between rotating magnetic field and rotor conductors is synchronous speed  $N_s$ ; under this condition let the per phase generated emf in rotor circuit be  $E_2$ .

$$\therefore \frac{E_2}{ph} = 4.44 N_{phr} \phi_1 f_1 K_{dr} K_{pr}$$

$$\frac{E_2}{ph} = 4.44 N_{phr} \phi_1 f_1 K_{wr}$$

$K_{wr}$  = Rotor winding factor

- But during running conditions the frequency of the rotor becomes, running with speed  $N_r$

$$\frac{P(N_s - N_r)}{120} = \frac{PsN_s}{120} = sf_1$$

$$\therefore f_r = sf_1$$

$\therefore$  Emf under running conditions is

$$E = \sqrt{2}\pi f_r K_{w2} N_{phr} \phi_1 = sE_2$$

- Rotor leakage reactance =  $2\pi$  (Rotor frequency) (Rotor leakage Inductance)

$$\therefore \text{Rotor leakage reactance at stand still} = 2\pi f_1 l_2 = x_2\Omega$$

- Rotor leakage reactance at any slips =  $2\pi f_2 l_2 = s x_2\Omega$

- Rotor leakage impedance at stand still =  $\sqrt{r_2^2 + x_2^2}$

- At any slip  $s$ , rotor =  $\sqrt{r_2^2 + (sx_2)^2}$

- Per phase rotor current at any slip  $s$  is given by

$$I_2 = \frac{sE_2}{\sqrt{r_2^2 + (sx_2)^2}} = \frac{E_2}{\sqrt{(r_2/s)^2 + x_2^2}}$$

- The rotor current  $I_2$  lags the rotor voltage  $E_2$  by rotor power factor angle  $\theta_2$  given by

$$\theta_2 = \tan^{-1} \frac{sX_2}{r_2}$$

- Per phase power input to rotor is

$$P_g = E_2 I_2 \cos \theta_2$$

$$\cos \theta_2 = \frac{\text{Per phase rotor resistance}}{\text{Per phase rotor impedance}} = \frac{r_2 / s}{\sqrt{(r_2 / s)^2 + (x_2)^2}}$$

$$\therefore P_g = E_2 I_2 \times \frac{r_2 / s}{\sqrt{(r_2 / s)^2 + (x_2)^2}} = \frac{E_2}{\sqrt{(r_2 / s)^2 + (x_2)^2}} \times I_2 \frac{r_2}{s} = I_2^2 \frac{r_2}{s}$$



- $P_g$  is the power transferred from stator to rotor across the air gap. Therefore,  $P_g$  is called air gap power

$$P_g = I_2^2 \frac{r_2}{s} = I_2^2 r_2 + I_2^2 r_2 \left[ \frac{1-s}{s} \right]$$

$$P_g = (\text{Rotor ohmic loss}) + \text{Internal mechanical power developed in rotor } (P_m) = sP_g + (1-s)P_g$$

$$\therefore P_m = (1-s)P_g = I_2^2 r_2 \left[ \frac{1-s}{s} \right]$$

$$\text{Rotor ohmic loss} = \left[ \frac{s}{1-s} \right] P_m = sP_g$$

- Internal (or gross) torque developed per phase is given by

$$T_e = \frac{\text{Internal mechanical power developed in rotor}}{\text{Rotor speed in mechanical radian per sec}}$$

$$T_e = \frac{P_m}{\omega_r} = \frac{(1-s)P_g}{(1-s)\omega_s} = \frac{P_g}{\omega_s}$$

- Electromagnetic torque  $T_e$  can also be expressed as

$$T_e = \frac{P_g}{\omega_s} = \frac{1}{\omega_s} \times \frac{I_2^2 r_2}{s} = \frac{\text{Rotor ohmic loss}}{(\omega_s) \text{ slip}}$$

$$\therefore T_e = \frac{\text{Rotor ohmic loss}}{(\omega_s) \text{ slip}}$$

- Power available at the shaft can be obtained from  $P_g$  as follows. Output or shaft power,

$$P_{sh} = P_m - \text{Mechanical losses}$$

- Mechanical losses imply friction and windage losses.

$$P_{sh} = P_g - \text{Rotor ohmic loss} - \text{Friction and windage losses} = \text{Net mechanical power output or net power output output or shaft torque}$$

$$T_{sh} = \frac{P_{sh}}{\text{Rotor speed}} = \frac{P_{sh}}{(1-s)\omega_s}$$

- If the stator input is known. Then air gap power  $P_g$  is given by  $P_g = \text{stator power input} - \text{stator } I^2R \text{ loss} - \text{stator core loss}$ .

- Ratio of Rotor input power, rotor copper losses and gross mechanical output is

$$\frac{I_r^2 R_2}{s} : I_r^2 R_2 : I_r^2 R_2 \left[ \frac{1}{s} - 1 \right]$$

$$\Rightarrow 1 : s : (1-s)$$

$$\therefore \text{Rotor copper losses} = s \times \text{Rotor input}$$

$$\text{Gross Mechanical output} = (1-s) \times \text{Rotor input}$$

$$\text{Rotor copper losses} = (\text{Gross mechanical output}) \times \frac{s}{1-s}$$

Efficiency of the rotor is approximately equal to

$$\eta_{\text{rotor}} = \frac{\text{Gross mechanical power output}}{\text{Rotor input}}$$

$$\frac{(1 - s)\text{Rotor input}}{\text{Rotor input}} = 1 - s = 1 - \frac{N_s - N}{N_s} = \frac{N}{N_s}$$

$$\eta_{\text{rotor}} \approx \frac{N}{N_s}$$

Total torque is

$$T_e = \frac{m}{\omega_s} \times \frac{V_e^2}{\left[ R_e + \frac{r_2}{s} \right]^2 + (X_2 + X_e)^2} \times \frac{r_2}{s} \text{ Nm}$$

m is the number of stator phases. Torque equation can be written as

$$T_e = \frac{m}{\omega_s} \times I_2^2 \times \frac{r_2}{s} = \frac{m}{\omega_s} \times \text{rotor input per phase.}$$

Thus, the slip  $s_{mT}$  at which maximum torque occurs is given by

$$s_{mT} = \frac{r_2}{\sqrt{R_e^2 + X^2}}$$

Substituting the value of maximum slip in the torque equation, gives maximum torque

$$T_{em} = \frac{m}{\omega_s} \times \frac{V_e^2}{2X_2}$$

If stator parameters are neglected then applying maximum transfer theorem to  $\frac{r_2}{s}$  then  $\frac{r_2}{s} = X_2$

Slip corresponding to maximum torque is

$$s_m = \frac{r_2}{X_2} \text{ (Breakdown slip)}$$

$$N_m = N_s(1 - s_m)$$

$$\Rightarrow N_m = N_s \left( 1 - \frac{R_2}{X_2} \right)$$

$N_m$  is the stalling speed at the maximum torque.

### Starting Torque:

At starting, slip  $S = 1.00$ , starting torque is given by

$$\text{Test} = \frac{mV_e^2}{\omega_s} \times \frac{r_2}{(R_e + r_2)^2 + X_2}$$

### Motor Torque in terms of $T_{em}$ :

- The torque expression of an induction motor can also be expressed in terms of maximum torque  $T_{em}$  and dimension less ratio  $\frac{S}{s_{mT}}$ . In order to get a simple and approximate expression, stator resistance  $r_1$ , or the stator equivalent resistance  $R_e$ , is neglected.

**Rajasthan RVUNL**

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

$$\therefore \frac{T_e}{T_{em}} = \frac{2X}{\left(\frac{r_2}{s}\right)^2 + X^2} \times \frac{r_2}{s}$$

- Since  $r_1$  or  $R_e$  is neglected

$$\frac{T_e}{T_{em}} = \frac{2X}{\left(\frac{r_2}{s}\right)^2 + X^2} \times \frac{r_2}{s}$$

- The slip at which maximum torque occurs is

$$S_{mT} = \frac{r_2}{X} \quad \therefore r_2 = S_{mT}X$$

$$\therefore \frac{T_e}{T_{em}} = \frac{2X}{\left[\frac{S_{mT}X}{s}\right]^2 + X^2} \times \frac{S_{mT}X}{s}$$

$$\Rightarrow \frac{T_e}{T_{em}} = \frac{2}{\frac{S_{mT}}{s} + \frac{s}{S_{mT}}}$$

$$T_e = \frac{2T_{em}}{\frac{S_{mT}}{s} + \frac{s}{S_{mT}}}$$

### Losses and Efficiency:

There are three cases in iron losses.

**Case (i):** If the ratio of voltage to frequency is constant and flux is also constant then:

Iron loss = Hysteresis loss + eddy current loss

$$P_h = K_h + B_m^{1.6}, \quad P_e = K_e f^2 B_m^2$$

Given:  $\frac{V}{f}$  is constant. As  $B_m \propto \frac{V}{f}$

$\Rightarrow B_m$  is constant.

$$\therefore P_h \propto f \quad \text{and} \quad P_e \propto f^2$$

**Case (ii):** If the ratio of voltage to frequency is not constant and flux is also not constant

$$\Rightarrow \frac{V}{f} \neq \text{const} \quad \phi \neq \text{const}$$

$$P_h = K_h f B_m^{1.6} \quad P_e = K_e f^2 B_m^2$$

$$\therefore P_h \propto V^{1.6} f^{-0.6} \quad P_e \propto V^2$$

**Case (iii):** If frequency is constant and voltage is variable then:

$$P_h = K_h f B_m^{1.6} \quad P_e = K_h f^2 B_m^2$$

$$= K_h f \left(\frac{V}{f}\right)^{1.6}$$

$$P_h \propto V^{1.6} \quad P_e \propto V_1^2$$

- Short circuit current with normal voltage applied to stator is

$$I = I_{br} \times \frac{V}{V_{br}}$$

$I$  = Short circuit current with normal voltage

$I_{br}$  = Short circuit current with voltage  $V_b$ ,

- Power factor on short circuit is found from

$$P_{br} = \sqrt{3}V_{br}I_{br} \cos \phi_{br}$$

$$\Rightarrow \cos \phi_{br} = \frac{P_{br}}{\sqrt{3}V_{br}I_{br}}$$

- As  $P_{br}$  is approximately equal to full load copper losses

$$R_{br} = \frac{P_{br}}{I_{br}^2}$$

The blocked rotor impedance is

$$Z_{br} = \frac{V_{br}}{I_{br}}$$

$$\therefore \text{Blocked rotor reactance} = X_{br} = \sqrt{Z_{br}^2 - R_{br}^2}$$

Efficiency of induction machines:

$$\text{Generally, efficiency} = \frac{\text{Output power}}{\text{Input power}}$$

$$\therefore \text{Efficiency of induction motor} = \frac{\text{Net mechanical output}}{\text{Electrical power input}}$$

$$\therefore \text{Efficiency of induction generator} = \frac{\text{Net electrical output}}{\text{Mechanical power input}}$$

$$\therefore \frac{GD}{GF} = \frac{P_{sc} - 3I_{sc}^2 r_1}{3I_{sc}^2 r_1}$$

$$\text{Wound rotor: } \frac{GD}{GF} = \frac{I_2^2 r_2}{I_1^2 r_1} = \frac{r_2}{r_1} \left( \frac{I_2}{I_1} \right)^2$$

### Direct-on line (across the line) starting:

- The relation between starting torque and full load torque is

$$T_e = \frac{1}{\omega_s} \times I_2^2 \frac{r_2}{s}$$

$$\therefore \frac{T_{e,st}}{T_{e,ft}} = \frac{I_{2,st}^2 \frac{r_2}{r_1}}{I_{2,ft}^2 \frac{r_2}{S_{f1}}} = \left[ \frac{I_{2,st}}{I_{2,ft}} \right]^2 \times S_{f1}$$

The above equation valid for rotor resistance remains constant.

$$\frac{T_{e,st}}{T_{e,f1}} = \left[ \frac{I_{st}}{I_{f1}} \right]^2 \times S_{f1}$$

Where,

$$\frac{I_{st}}{I_{f1}} = \frac{(\text{Effective rotor to stator turns ratio}) I_{2,st}}{(\text{Effective rotor to stator turns ratio}) I_{2,s1}}$$

- Per phase short – circuit current at stand still (or at starting) is,

$$I_{sc} = \frac{V_1}{Z_{sc}}$$

Where,  $Z_{sc} = (r_1 + r_2) + j(x_1 + x_2)$

Here shunt branch parameters of equivalent circuit are neglected.

- Therefore, for direct switching.

$$I_{st} = I_{sc} = \frac{V_1}{Z_{sc}}$$

$$\therefore \frac{T_{est}}{T_{esf}} = \left[ \frac{I_{sc}}{I_{f1}} \right]^2 S_{f1}$$

**Stator resistor (or reactor) starting:**

Since per phase voltage is reduced to  $xv$ , the per phase starting current  $I_{st}$  is given by

$$I_{st} = \frac{xV_1}{Z_{sc}} = xI_{sc}$$

As before  $\therefore \frac{T_{est}}{T_{esf}} = \left[ \frac{I_{sc}}{I_{f1}} \right]^2 S_{f1} = \left[ \frac{xI_{sc}}{I_{f1}} \right]^2 S_{f1}$

- In an induction motor, torque  $\propto$  (Voltage)<sup>2</sup>

$$\therefore \frac{\text{Starting torque with reactor starting}}{\text{Starting torque with direct switching}} = \left[ \frac{xV_1}{V_1} \right]^2 = x^2$$

**Auto transformer starting:**

- Per phase starting current from the supply mains is  $I_{st} = x^2 I_{sc}$

$$\frac{T_{e,st}}{T_{e,f1}} = \frac{\text{Per phase starting current in motor winding}}{\text{Per phase motor full load current}} \times S_{f1}$$

$$\frac{T_{e,st}}{T_{e,f1}} = \frac{I_{st} I_{sc}}{I_{f1}^2} \times S_{f1}$$

$$\frac{T_{e,st} \text{ with an auto transformer}}{T_{e,st} \text{ with direct switching}} = \left[ \frac{xV_1}{V_1} \right]^2 = x^2$$

**Star – Delta method of Starting:**

## Rajasthan RVUNL

A Technical Course for AEN & JEN (Electrical)

START FREE TRIAL

- $$\frac{\text{Starting torque with star delta starter}}{\text{Starting torque with direct switching in delta}} = \frac{\left[\frac{V_L}{\sqrt{3}}\right]^2}{[V_L]^2} = \frac{1}{3}$$

∴ Star delta starter also reduces the starting torque to one-third of that produce by direct switching in delta.

- With star – delta starter, a motor behaves as if it were started by an auto transformer starter with  $x = \frac{1}{\sqrt{3}} = 0.58$  i.e. with 58% tapping.

- $$\frac{\text{Starting torque with star delta starter, } T_{e, \text{st}}}{\text{Starting torque with direct switching in delta, } T_{e, \text{fd}}} = \frac{\frac{1}{w_s} (I_{\text{st}, y})^2 \frac{r_2}{1}}{\frac{1}{w_s} (I_{\text{st}, d})^2 \frac{r_2}{S_{f1}}}$$

$$= \frac{\left[\frac{1}{\sqrt{3}} I_{\text{st}, d}\right]^2}{(I_{f1, d})^2} \times S_{f1} = \frac{1}{3} \left[\frac{I_{\text{sc}d}}{I_{f1d}}\right]^2 \times S_{f1}$$

\*\*\*